

Inspection Points

- Scratches
- Burn/Weld Marks
- Tampered Bolts/Rivets
- Fresh Grease
- Fresh Paint
- Silicone
- Fiberglass/Bondo Patchwork
- Odor Masking Substances
- After Market Modification



U.S. Customs and
Border Protection



Field Operations

